

LEGIONELLA RISK ASSESSMENT

THE PREVENTION AND CONTROL OF LEGIONNAIRES' DISEASE



Client:	Wessex RFCA		
Site:	Wyvern Barracks Building 3		
Address:	Wyvern Barracks, Barrack Road, Exeter, EX2 6AR		
Risk Rating:	Medium		
Report Ref:	AQST/LRA/331		
Surveyed By:	Jon Barton		
Survey Date:	11 th -13 th March 2024		
Report Date:	15 th March 2024		
Recommended Review Date:	March 2026		



Contents

- 1. **Executive Summary**
- 2. Summary of Recommendations and Risk Rating
- 3. General Precautions and Actions
- 4. General Site Information and Scope of Risk Assessment
- 5. Lines of communication and responsibility
- 6. **Survey Details**
- 6.1 Mains Water Supply Survey
- 6.2 Other Assets
- 6.3 Cold Water Storage Tank Survey
- 6.4 Hot Water Storage Vessel Survey
- 6.5 Showers
- 6.6 Dead legs
- 6.7 Point of Use Water Heaters
- 6.8 Fire Hoses.
- 6.9 Water Softeners
- 7. **Outlets Sheet**
- 8. **Domestic Water Schematic Drawings**
- 9. Photographic Evidence
- 10. Asset Register Summary
- 11. Water Treatment and hygiene experience and training details
- 12. Legislations Appendice A - Legislation and Codes of Practice Appendice B - Summary of Approved Code of Practice Appendice C - ACOPL8 (Revised) and HSG274 Parts 1, 2 and 3 summary











1. EXECUTIVE SUMMARY

This document is intended to identify the risk of developing legionnaire's disease from the building water system. The Health and Safety Executive Approved Code of Practice recommends Risk Assessments should be reviewed on a regular basis and in accordance with the current ACOP recommendations.

The Health and Safety commission issued an Approved Code of Practice for "Prevention of Legionellosis (including legionnaires' disease)" which came into effect on 15th January 1992, requiring a risk assessment to be undertaken. Guidance notes were issued by the Health and Safety Executive in the form of HS(G)70 and on the 8th January 2001 the Approved Code of Practice L8 came into force and BS8580:2019. This risk assessment is structured around the requirements of these documents, ACOPL8 revised and HSG274 Parts 1, 2 and 3 and The Water Regulations Guide.

Legionellosis is the term used for infections caused by legionella pneumphila and other bacteria from the family Legionellaceae. Legionnaire's Disease is a pneumonia that principally effects those who are susceptible due to age, illness, immunosuppression, smoking etc. and may be fatal. Legionellae can also cause less serious illnesses that are not fatal or permanently debilitating but which can affect all people. Infection is attributed to inhaling legionellae, either those water droplets which are small enough to penetrate deeply into the lung, or in droplet nuclei (particles left when water has evaporated). Legionellae are widespread in natural sources of water. They may enter man-made systems or water services, where they can multiply under certain conditions, and if there is a means of creating the transmitting water droplets, people in the vicinity may be at risk. Between 200-400 cases of legionellosis are reported in England and Wales every year.

For a risk to be present a chain of events has to occur:

- * System infection
- * Legionellae proliferation enhanced by system conditions
- * Aerosol formation
- * Inhalation of aerosol by susceptible individual

Since aerosol formation and inhalation is difficult to avoid the onus falls on the operator to prevent system infection and to eliminate conditions in which legionellae thrive. The aim is to reduce the risk to an acceptable level by controlling the conditions necessary for proliferation of the bacterium. As a general rule, in practice this means: Keeping the hot water storage temperature at greater than 60°C, maintaining cold water temperatures at less than 20°C, keeping water systems clean and in good condition and controlling contamination of the water systems. It is, however, understood that some small systems, particularly when instantaneous water heaters are being used as a hot water source, may not be able to achieve these parameters and further recommendations will be given as required.

In order to achieve this aim, a detailed legionellosis risk assessment has been carried out, the results of which are used to produce recommendations for the control of the bacterium.

Full details of the required actions are enclosed.









This risk assessment does not involve the preparation of the written scheme of control, but rather provides information that is critical to its preparation, improvement, and review.

Ensuring that there is a written scheme of control is a legal requirement of the duty holder, though they might instruct the risk assessor to advise or prepare the scheme of control on their behalf as a separate commission. It is important that operation and maintenance individuals are consulted.

The survey and assessment were conducted by Jon Barton of Aquastat in March 2024 on behalf of the RFCA.

This risk assessment only covers those water systems identified and made accessible to the assessor at the time of the survey.

Location: Within the Wyvern Barracks compound.

Site Description: Exeter university HQ building.

Site Layout: Two storey building with kitchens, toilets, showers, and stores.

Mains Cold Water Services (MCWS): Mains water supplies CWST1-2 and some cold outlets within the building.

Cold Water Storage Tank(s) (CWST) and Cold-Water Down Services (CWDS): There are two linked tank located in the roof space. These supply the make-up to Cal 2 and also multiple cold outlets within the building and the cold supply to showers.

Hot Water Storage Vessel(s) and Hot Water Systems (HWS): There is one hot water storage vessel located in the boiler room. This supplies hot water via a circulatory flow and return system to the majority of hot outlets within the building and also the hot supply to all showers.

Thermostatic Mixer Valves (TMV) and Thermostatic Mixer Taps (TMT): There are TMVs associated showers.

Showers and Spray Outlets: There are multiple showers within the male and female ablutions.

Water Heaters: There are three low volume water heater supplying hot water to their respective areas.

Expansion Vessels: None on site.

Water Softeners: None on site.











2. SUMMARY OF RECOMMENDATIONS and RISK RATING

This Risk Assessment has been carried out in order to ascertain the possible risk of contracting Legionellosis, including Legionnaires' disease, from water systems and to identify the maintenance activities required to control or prevent the risk from Legionella, including any remedial works that may be required to improve upon the findings of this assessment.

The water systems throughout this building, unless otherwise stated, have been surveyed utilising the specific asset survey forms within section six of this assessment. Each question is answered and, depending upon the survey findings, a risk score is allocated utilising the matrix below.

This matrix is designed to indicate possible risk or problematic areas within the assets or water systems.

Multiple questions will be asked for all aspects of the water asset or services present on the site.

The results from these questions will then be scored upon the risk of Legionella. The key to this scoring is:

KEY

	Risk Level	Action
N/A	The risk from Legionella is not applicable under normal operating conditions.	No action required for the control of Legionella. Other remedial actions may be applicable.
LOW	There is a low risk under normal operating conditions.	No additional actions required above ensuring compliance with ACoP L8
MEDIUM	There is a medium risk under normal operating conditions.	Implement risk reduction measures in compliance with ACoP L8 e.g.: Remedial Works or Control Scheme.
нідн	There is a high risk under normal operating conditions.	Implement Immediate or more radical risk reduction measures e.g. Emergency disinfection. / System changes or prohibition of use.

Where Legionella management and training is insufficient or lines of communication are not established, which are quantifiable on the surveyor's experience and knowledge.

The assessor will use the knowledge of others as well as his own technical knowledge in the judgement of the water systems assessed within this document.

We cannot guarantee that all pipe work passing underground or through floors, walls and ceilings has been traced, and it is possible that certain system dead-ends or dead-legs may not have been identified. As a result, the schematic diagram(s) contained within this report only details the visible or assumed pipe work.

Whilst every effort has been made to ensure the accuracy of the content of this document, Aquastat will accept no responsibility for any omissions that are not included.

Page **5** of **35**







OVERALL SYSTEM RISK STATUS

The susceptibility of personnel upon this site to the cause and effects of Legionnaires' disease have been assessed within the known range for specific Legionella susceptibility. Understandably, not every person has been interviewed to their susceptibility. Therefore, assumptions have been made as appropriate, based upon visual observations and communication during this assessment.

Population Profile		
Health of Users	Young healthy adults represent a low/moderate risk from legionella exposure. Older adults represent a moderate risk	
Property Occupancy	Approx. 300 people attend once a week. Some permanent site staff are based in the building.	

Risk Assessment		LOW 1-2	MEDIUM 3	HIGH 4-5
Are conditions suitable for multiplication of bacteria including Legionella Pneumophila? <i>E.g. where optimum</i> <i>temperatures for microbial growth and stagnation occur,</i> <i>e.g. dead legs and infrequently used outlets.</i>			3	
Are nutrients present within the systered and oth <i>E.g. sludge, scale, rust, algae and oth</i>	em? er organic matter.			4
Is there a means of creating and disse droplets? <i>E.g. aerosol generated by a</i>			4	
Are high risk groups using the water s E.g. persons over the age of 45, those underlying health issues and compron		3		
Are control systems in place and chec carried out? E.g. Is monitoring being intervals? is it effective? Have there b cases identified?		3		
isk Factor 17 MEDIUM				
Low 5-11; Medium 11-19; High 19+				
Important Note: Low risk does not mean no risk and all recommendations highlighted within this document should be addressed.				









<u>SYST</u>	EM TYPES	RISK
	COLD WATER MAINS:	RATING
	Exposed pipework requires insulating in places.	Medium
	Uninsulated pipework passes radiators in the GF male WC which is causing unwanted heat	
	gain.	
	Actioned date: Company/initials:	
	COLD WATER STORAGE TANKS:	
	Both CWST's require cleaning and disinfection.	High
	Actioned date: Company/initials:	
	The laundry room kitchen and some cold outlets within the main kitchen are supplied from	Low
	the tanks.	
	Please be aware that the internal condition of the tanks does not meet potable water	
	requirements.	
	Label the affected outlets as 'non-drinking water'.	
	See schematics for tank fed water locations.	
	Actioned date: Company/initials:	
	HOT WATER CALORIFIERS:	
	Satisfactory	
	POINT OF USE WATER HEATERS:	
	The GF right side female WC water heater was not switched on.	Medium
	Confirm this is operational, stores water >50.C and is in constant use.	
	Actioned date: Company/initials:	
	SHOWERS AND SPRAY OUTLETS:	
	Two of the male showers have been placed out of order.	High
	Reinstate flow to both showers.	U
	Actioned date: Company/initials:	
	GENERAL: Control Schemes	
	There is a new logbook on site. This logbook new logbook should contain the following	High
	information:	U
	-A copy of this risk assessment	
	-An up to date management structure listing the on-site responsible people	
	-The RFCA legionella policy	
	-Aquastat's reports (or add a statement showing where these records are kept)	
	-Evidence of any servicing/maintenance	
	-Results from any legionella or TVC samples	
	Actioned date: Company/initials:	
	The site responsible person should receive the appropriate legionella training.	High
	It is imperative that someone on site understands why control measures are put in place.	
	The site responsible person should also be familiar with the RFCA legionella policy and should	
	ensure that they are fulfilling the requirements of this policy.	
	Actioned date: Company/initials:	
	The site responsible person (or deputy RP) should also oversee departmental flushing and	High
	ensure (if outlets have been identified as infrequently used) that flushing records are up to	
	date.	
	Possible infrequently outlets include:	
	-Kitchen bib tap	
	-Bar area (isolated)	
	-RHS ground floor toilets	
	-All showers	
	Discoloured water observed from the FF female ablutions and the kitchen bib tap.	
	Actioned date: Company/initials:	
	Dead legs require attention. See section 6.6	High
	Actioned date: Company/initials:	









LOG BOOK DOCUMENTATION/RECORD KEEPING

PREMISES : Wyvern Barracks - Building 3

Is there a water hygiene log book on site	YES	
If yes - please confirm the following:		
Where is the log book located?	Building 22	
Name and position of person responsible for log book?	Dean Bywoo	d
Has this person received the appropriate training in Legionella Control & is there evidence		NO
Does the log book contain a copy of the existing Legionella Risk Assessment?	YES	
Does the log book contain written scheme for Legionella control?		NO
Are there any non-conformances outstanding from previous Risk Assessments		NO
Are monthly temperature checks being taken and regularly recorded?	YES	
Is there an attendance log sheet in the book?	YES	
If applicable are showers being dismantled, cleaned and disinfected on a regular basis and regularly recorded?	YES	
Are CWST's and Hot Water Storage Vessels being monitored on a 6 monthly or Annual basis?	YES	
If applicable are little used outlets being flushed weekly and regularly recorded?		NO
If applicable are mixer valves being serviced on an annual basis and regularly recorded?	YES	
If no log book on site, please advise the following:		
Is the log book held at a different location?		
If yes - please give name of responsible person and full	We understand copies of all	
address and telephone number	related works are held centrally and uploaded onto a shared drive	
Is there an asset register on site?	YES	
Are Safety Data Sheets held for chemicals associated with Legionella control?		NO

If there is no log book on site, or held at a different location this represents a non-compliance with the Approved Code of Practice

All records and inspection reports should be kept in the site legionella control logbook for a period of 5 years

If the log book is held at a different premises, it is the duty of the responsible person to ensure the above checks are carried out and fully recorded.









Control Scheme	ls it Actioned	Carried out by whom	Frequency	Is it logged	Comments
Infrequently used outlet flushing	No	Site	Weekly	No	Required Weekly
Hot and cold sentinel outlets temperature monitoring	Yes	Aquastat	Monthly	Yes	Required Monthly
Hot and cold representative outlet monitoring	Yes	Aquastat	Monthly	Yes	Required Monthly
Shower, rinse hose, spray outlet descales	Yes	Aquastat	Quarterly	Yes	Required Quarterly
Hot Water Storage Vessel flow and return temperature monitoring	Yes	Aquastat	Monthly	Yes	Required Monthly
Hot Water Storage Vessel internal inspections	Yes	Aquastat	Annually	Yes	Required Annually
CWST inspections	Yes	Aquastat	Annually	Yes	Required Annually
CWST temperature monitoring	Yes	Aquastat	Annually	Yes	Required Annually
CWST clean and disinfection	Yes	Aquastat	As required	Yes	When required
Risk Assessment	Yes	Aquastat	Every two years	Yes	This assessment replaces out of date LRA
Log Book Audit	No	Site	Annually	No	Log book required for implementation of control schemes
Regular reviews of Control schemes, Training and competency.	No	Site	Annually	No	Required
Sampling (Legionella or TVC)	Yes	Aquastat	Annually	Yes	As Required





3. GENERAL PRECAUTIONS AND ACTIONS

The list below indicates the essential practical maintenance/management actions for which the head of site is responsible for ensuring.

- 1. Operate hot water systems at or above the approved minimum temperature. Storage should be above 60°C. Outlet (tap) temperatures should be above 50°C (unless fitted with a thermostatic mixing valve (TMV). Terminal fittings or communal showers in buildings used by young children/the very old and those with sensory loss should be supplied with water through thermostatic mixing valves so that the temperature of the water discharged at the outlets does not exceed 43 degrees C.
- 2. Maintain cold systems at or below the approved maximum water temperature. It is acceptable for the temperature to be 2°C greater than the incoming mains water temperature. However, this should not exceed 25°C.
- 3. Infrequently used outlets should be removed and any dead legs capped off at the main circulation or added to a flushing regime. Where showers are required and retained, they are to be run at least once per week or if possible, daily. Shower heads should be cleaned and disinfected in accordance with HSG274 at least on a quarterly basis.
- 4. Avoid the creation of unnecessary aerosols of water.
- 5. Ensure that the system is cleaned and disinfected if you become aware of any activity or occurrence, which you believe, may jeopardise water hygiene. Should a disinfection be required an Aquastat representative could advise?
- 6. Maintain records of temperature checks regular temperature checks should be taken from selected tap outlets after one running minute. A standard UKAS calibrated thermometer held under the water flow is all that is needed. The temperature should be recorded in the legionella log book. The results recorded on a simple temperature record table. When temperatures consistently fail to comply with the approved ranges your water hygiene company should be contacted for further guidance and advice.
- 8. When the site is unused for more than 72 hours it is advisable to run hot and cold tap outlets on entry to the building to ensure stagnant water is removed from the pipework before use. **
- 9. After plumbing (i.e. new water heater or pipework alterations etc.) have been carried out, the site should be chlorinated to BS8558 standard it may be necessary to fit an injection point to enable this process.
- 10. All outside bib taps should be fitted with a double check valve to prevent back flow.
- 11. Buildings with mixtures of lead, copper and iron pipework should be considered for refit in the long-term budget.
- 12. Dedicated drinking water tap should be clearly labelled.













13. Intermittently Used Buildings:

- ** On entry to a building after period of closure one senior nominated person should ensure the following before any personnel are allowed to use the water systems.
- a. The furthest tap from the mains entry point should be turned on and flushed this will ensure that any water lying dormant within the building or trapped in the feed pipe from the mains supply is thoroughly flushed and allowing the cold water to attain towns water temperatures at outlets. Approximately 2-3 minutes constant running of a mains tap if the building is close to the towns water stop tap, or 10 minutes if over 100yds should be sufficient.
- b. Instantaneous water heaters are not designed to store hot water at 60 degrees as the guidelines suggest but we would recommend that the heaters are turned on and allowed at least 5 minutes for the temperature to rise to over 45 degrees C before use.
- 14. Positive Legionella Results
- 14.1 Positive Legionella results from a water system are reported to the client's responsible person by the fastest means available. This is usually a telephone call or email which will be confirmed by emailing the laboratory's analysis report and setting down in writing the initial corrective measures that we and/or our client should be undertaking.
- 14.2 The corrective measures advised will depend on individual circumstances and will be based on the guidance notes form HSE's ACOP HSG274 Parts 1,2,3 and will be instigated as quickly as possible after receiving an order from client.









4. **GENERAL SITE INFORMATION**

Building Description and type of use	University HQ building.
Approx. number of occupants and overall age group	Some permanent site staff and approx. 300 people once a week.
Normal operational hours of this building	Office hours and evenings as required.
On site contact name at date of LRA	Dean Bywood (Barrack Manager)

SCOPE OF RISK ASSESSMENT

- Non-intrusive Site inspection visit of the agreed survey site to determine the current condition and usage of plant associated with domestic water systems on site.
- Non-intrusive Site inspection visit of the agreed survey site to determine the current condition of the management control of plant associated with domestic water systems on site.
- Produce a written report to relay the results generated from the site visit.
 Produce a site-specific asset register.
 Produce a site-specific and up to date schematic of the water systems of the survey site.

The temperatures have been taken and recorded from all areas that were accessible to the assessor during the survey; however, in larger complex buildings a representative number of temperatures may only be taken and recorded.

The following areas of the site have not been assessed:

Location:	Assets:	Reason:
Various locked doors	Unknown	This is a military site. It is not reasonably practical to gain access to all locked doors.

These listed water systems will only be assessed for risk of Legionellosis and not for any other factor.

The extent of the Risk Assessment is reliant on information supplied from site at time of survey and on observable conditions.

Whilst every effort has been made to ensure the accuracy of the content of this document, Aquastat will accept no responsibility for any omissions.









5. LINES OF COMMUNICATION AND RESPONSIBILITY

At this site the following key contacts have been identified.

Duty holder: Individual with the legal responsibility to ensure that health and safety is managed effectively Mark Armstrong Wessex RF & CA Mount Street Taunton TA1 3QE 0.823 2.17940 Nominated on site responsible person: Individual appointed with and who has accepted responsibility under the authority of the duty holder for ensuring that for the control of Legionella all those assigned to carry out tasks are competent to do so. 0.823 2.17942 Nominated on site responsible person: Individual appointed with and who has accepted responsibility under the authority of the duty holder for ensuring that for the control of Legionella all those assigned to carry out tasks are competent to do so. 0.823 2.17942 Pupty on site responsible person: In a large undertaking there may be more than one responsible person 0.823 2.17942 Deputy on site responsible person: In a large undertaking there may be more than one responsible person wx-estatess@rfca.mod.uk Ramager) Barracks k Major Chris Mills (QM) Wyvern dean.bywood100@mod.gov.u Water Supply South West Water Peninsula House Rydon Lane Exeter 0.1392 446688 0.1392 446688 Contractor or Maintenance Wessex RF & CA Mount House Mount Street Taunton 0.1823 250116 0.1823 250116 Water Treatment Company for this assessment Aquasta		NAME	ADDRESS	TEL NOS
Mark ArmstrongWessex RF & CA Mount House Mount TA1 3QE01823 217940Nominated on site responsible person:Individual appointed with and who has accepted responsibility under the authority of the duty holder for ensuring that for the contractionWessex RF & CA Mount Street Taunton TA1 3QE01823 217942Nominated on site responsible person:In a large undertwick Mount Street Taunton TA1 3QE01823 217942Deputy on site responsible person:In a large undertwicking there may be more than or responsible persondean.bywood100@mod.gov.u BarracksDeputy on site responsible personDean Bywood (barrack manager)Building 22, Wyvern Barracksdean.bywood100@mod.gov.u Rydon Lane Exeter EX2 7HRWater Supply CompanyOuth West Water Mount Street Taunton Rydon Lane Exeter EX2 7HR01823 250116Mechanical contractor or maintenance companyWessex RF & CA Mount House Mount Street Taunton TA1 3QE01823 250116Water Treatment CompanyWessex RF & CA Mount House Mount Street Taunton TA1 3QE01823 250116Water Treatment CompanyAquastat AquastatMount House Mount Street Taunton TA1 3QE01823 250116Water Treatment CompanyAquastat Campany contactGary Ford 	Duty holder: Individu	al with the legal responsibility to	ensure that health and safety is i	managed effectively
Mount House Mount Street Taunton TA1 3QEwx-estatesn@rfca.mod.ukNominated on site responsible person:Individual appointed with and who has accepted responsibility under the authority of the duty holder for ensuring that for the control of Legionella all those assigned to carry out tasks are competent to do so.01823 217942 wx-estatess@rfca.mod.ukDeputy on site responsible person:In a large undertaking there may be more than one responsible person01823 217942 wx-estatess@rfca.mod.ukDeputy on site responsible person:In a large undertaking there may be more than one responsible persondean.bywood100@mod.gov.u BarracksWater Supply CompanyDean Bywood (barrack manager)Building 22, Wyvern Barracksdean.bywood100@mod.gov.u kerrWater Supply CompanySouth West WaterPeninsula House Rydon Lane Exeter Exet r Exet r01823 250116Mechanical contractor or maintenance companyWessex RF & CA Mount Street Taunton TA1 3QE01823 250116Water Treatment CompanyAquastatUnit N ~ The Old Parlour Purn House Farm, Bleadon Westor-Super-Mare Dord Parlour Purn House Farm, Bleadon Westor-Super-Mare Purn House Farm, Bleadon Westor-Super-Mare Dord Parlour Purn House Farm, Bleadon Westor-Super-Mare Purn House Farm, Bleadon Westo		Mark Armstrong	Wessex RF & CA	01823 217940
Mount Street Taunton TA1 3QEwx-estatesn@rfca.mod.uk war-estatesn@rfca.mod.ukNominated on site responsible person:Individual appointed with and who has accepted responsibility under the cathority of the duty holder for ensuring that for the control of Legionella all those assigned to carry out tasks are competent to do so.01823 217942Wessex RF & CA Mount Street Taunton TA1 3QE01823 21794201823 217942Deputy on site responsible person:In a large undertaking there may be more than one responsible personwx-estatess@rfca.mod.ukDeputy on site responsible personDean Bywood (barrack Mainger)Building 22, Wyvern Barracksdean.bywood100@mod.gov.u kWater Supply CompanySouth West WaterPeninsula House Rydon Lane Exeter EX2 7HR01823 250116Mechanical companyWessex RF & CA Mount House Mount Street Taunton TA1 3QE01823 250116Maintenance companyWessex RF & CA Mount Street Taunton TA1 3QE01823 250116Water Treatment company companyAquastatUnit N - The Old Parlour Purn House Farm, Bleadon Westor-Super-Mare North Somerset BS24 0QETel: 01934 811264 Email - enquiries@aquastat.co.ukWater Treatment company for Company for Company for Company for Company for Company contactCary Ford Gary Ford General ManagerAs above or email pusch bakemore@aquastat.co.ukWater Treatment company for Company for Company for Company for Company for Company for Company for Company for Company for Company contactCary Ford Gary Ford General ManagerAs above			Mount House	
Nominated on site responsible person:Individual appointed with and who has accepted responsibility under the authority of the duty holder for ensuring that for the control of Legionella all those assigned to carry out tasks are competent to do so.authority of the duty holder for ensuring that for the control of Legionella all those assigned to carry out tasks are competent to do so.01823 217942BaracksKelvin WalkerWessex RF & CA Mount House Mount Street Taunton TA1 3QE01823 217942Deputy on site responsible person:In a large undertaking there may be more than one responsible persondean.bwwood100@mod.gov.u kDeputy on site responsible person:Dean Bywood (barrack Major Chris Mills (QM)Building 22, Wyvern Barracksdean.bwwood100@mod.gov.u kWater Supply CompanySouth West WaterPeninsula House Rydon Lane Exeter EX2 7HR01392 446688Mechanical contractor or maintenance companyWessex RF & CA Mount House01823 250116Maintenance companyTaunton Taunton Taunton Taunton Taunton Taunton Taunton Taunton Taunton Taunton01823 250116Water Treatment Company of this assessmentAquastatUnit N - The Old Parlour North Somerset B524 OQETel: 01934 811264 Email - enquiries@aquastat.co.ukWater Treatment company for Complance tasksAquastatUnit N - The Old Parlour Purn House Farm, Bleadon General ManagerAs above or email gary.ford@aquastat.co.ukWater Treatment company for Complance tasksAquastatUnit N - The Old Parlour Purn House Farm, Bleadon Use blakemore@aqua			Mount Street	wx-estatesn@rfca.mod.uk
Nominated on site responsible person: Individual appointed with and who has accepted responsibility under the authority of the duty holder for ensuring that for the control of Legionella all those assigned to carry out tasks are competent to do so. Use set RF & CA 01823 217942 Image: Contract on the control of Legionella all those assigned to carry out tasks are competent to do so. Usessex RF & CA 01823 217942 Image: Contract on the control of Legionella all those assigned to carry out tasks are competent to do so. Usessex RF & CA 01823 217942 Image: Contract on the control of Legionella all those assigned to carry out tasks are competent manager) Usessex RF & CA 01823 217942 Image: Contract on the control of Legionella all those assigned to carry out tasks are competent manager) Deputy on site responsible person Deputy on site responsible person Image: Contract on the control of Legionella all those assigned to carry out tasks are competent contractor or maintenance South West Water Penisula House 01392 446688 Image: Contract or or maintenance Wessex RF & CA Mount House 01823 250116 Image: Contract or or maintenance Wessex RF & CA Mount House 01823 250116 Image: Contract or or maintenance Aquastat Unit N - The Old Parlour Purn House Farm, Bleadon Tel: 01934 811264 Image: Company for this assessment			Taunton TA1 3QE	
Kelvin Walker Wessex RF & CA Mount House Mount Street Taunton TA1 3QE 01823 217942 wx-estatess@rfca.mod.uk Deputy on site responsible person Dean Bywood (barrack manager) Building 22, Wyvern Barracks dean.bywood100@mod.gov.u k Water Supply Company Dean Bywood (barrack Major Chris Mills (QM) Wyvern Barracks 01392 446688 Water Supply Company South West Water Peninsula House Rydon Lane Exeter EX2 7HR 01823 250116 Mechanical contractor or maintenance company Wessex RF & CA Mount House Nount Street Taunton TA1 3QE 01823 250116 Metrical contractor or maintenance company Wessex RF & CA Mount House Nount Street Taunton TA1 3QE 01823 250116 Water Treatment Company for this assessment Aquastat Mount House Mount Street Taunton TA1 3QE 01823 250116 Water Treatment Company for this assessment Aquastat Unit N - The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 0QE Tel: 01934 811264 Email - enquiries@aquastat.co.uk North Somerset BS24 0QE As above or email gary.ford@aguastat.co.uk North Somerset BS24 0QE As above or email gary.ford@aguastat.co.uk North Somerset BS24 0QE As above or email louise.blakemore@aguastat.co.uk North Somerset BS24 0QE As above or email louise.blakemore@aguastat.co.uk Email - enquiries@aguastat.co.uk North Somerset BS24 0QE Tel: 01934 811264 Email - enquiries@aguastat.co	Nominated on site re authority of the duty ho to do so.	esponsible person: Individual de Ider for ensuring that for the contract of t	appointed with and who has acce trol of Legionella all those assigne	pted responsibility under the ed to carry out tasks are competent
Mount House Mount Street Taunton TA1 3QEwx-estatess@rfca.mod.uk wx-estatess@rfca.mod.ukDeputy on site responsible personDean Bywood (barrack maager)Building 22, Wyvern Barracksdean.bywood100@mod.gov.u kWater Supply CompanyDean Bywood (barrack maager)Building 22, Wyvern Barracksdean.bywood100@mod.gov.u kWater Supply CompanySouth West WaterPeninsula House Rydon Lane Exeter EX2 7HR01392 446688Mechanical contractor or Maintenance companyWessex RF & CAMount House Mount Street Taunton TA1 3QE01823 250116Methanical contractor or maintenance company for this assessmentWessex RF & CAMount House Mount Street Taunton TA1 3QE01823 250116Water Treatment company for this assessmentAquastatUnit N - The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 QQETel: 01934 811264 Email - enquiries@aquastat.co.ukWater Treatment company for as par H5C724AquastatUnit N - The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North SomersetTel: 01934 811264 Email - enquiries@aquastat.co.ukWater Treatment company for as are H5C724AquastatUnit N - The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North SomersetTel: 01934 811264 Email - enquiries@aquastat.co.uk		Kelvin Walker	Wessex RF & CA	01823 217942
Image: constant series and the series of t			Mount House	
Deputy on site responsible person: in a large undertaking there may be more than or responsible personDean Bywood (barrack manager)Building 22, Wyvern Barracksdean.bywood100@mod.gov.u kDeputy on site responsible personDean Bywood (barrack Major Chris Mills (QM)Wyvern Barracksdean.bywood100@mod.gov.u kWater Supply CompanySouth West WaterPeninsula House Rydon Lane EX2 7HR01392 446688Mechanical contractor or Maintenance companyWessex RF & CAMount House Mount Street Taunton TA1 3QE01823 250116Electrical companyWessex RF & CAMount House Mount Street Taunton TA1 3QE01823 250116Water Treatment Company for this assessmentAquastatUnit N - The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 OQETel: 01934 811264 Email - enquiries@aquastat.co.ukWater Treatment company for ass per HS6274AquastatUnit N - The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 OQEAs above or email gary.ford@aquastat.co.ukWater Treatment company for as a per HS6274AquastatUnit N - The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 OQEAs above or email gary.ford@aquastat.co.uk			Mount Street	wx-estatess@rfca.mod.uk
Deputy on site responsible person: In a large undertaking there may be more than one responsible person Deputy on site responsible person Dean Bywood (barrack manager) Building 22, Wyvern Barracks dean.bywood100@mod.gov.u k Major Chris Mills (QM) Wyvern Barracks Imager) dean.bywood100@mod.gov.u k Water Supply Company South West Water Peninsula House Rydon Lane Exeter 01392 446688 Mechanical contractor or Maintenance Wessex RF & CA Mount House Mount Street 01823 250116 Electrical contractor or maintenance Wessex RF & CA Mount House Mount Street 01823 250116 Water Treatment Company Aquastat Unit N – The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare Tel: 01934 811264 Email - enquiries@aquastat.co.uk Water Treatment company for this assessment Afuastat Unit N – The Old Parlour Purn House Farm, Bleadon North Somerset BS24 OQE As above or email gary ford@aquastat.co.uk Water Treatment company for Compiny contact Gary Ford General Manager As above or email gary ford@aquastat.co.uk Water Treatment company for Compiny for Aquastat Unit N – The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare As above or email gary ford@aquastat.co.uk Water Treatment company for A			Taunton TA1 3QE	
Deputy on site responsible person Dean Bywood (barrack manager) Building 22, Wyvern Barracks dean.bywood100@mod.gov.u k Water Supply Company Major Chris Mills (QM) Wyvern Barracks 01392 446688 Water Supply Company South West Water Peninsula House Rydon Lane 01392 446688 Mechanical contractor or Maintenance Wessex RF & CA Mount House Mount Street 01823 250116 Electrical company Wessex RF & CA Mount House Mount Street 01823 250116 Electrical company Wessex RF & CA Mount House Mount Street 01823 250116 Vater Treatment Company for this assessment Aquastat Unit N – The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 OQE Tel: 01934 811264 Email - enquiries@aquastat.co.uk Vater Treatment company for this assessment 2 nd Company contact Gary Ford General Manager As above or email louise.blakemore@aguastat.co.uk Water Treatment company for compiance tasks Aquastat Unit N – The Old Parlour Purn House Farm, Bleadon Nerston-Super-Mare As above or email louise.blakemore@aguastat.co.uk	Deputy on site respo	nsible person: In a large under	rtaking there may be more than c	one responsible person
responsible person manager) Barracks k Major Chris Mills (QM) Wyvern Barracks Water Supply Company South West Water Peninsula House Rydon Lane Exeter 01392 446688 Mechanical contractor or Maintenance company Wessex RF & CA Mount House Mount Street Taunton TA1 3QE 01823 250116 Electrical contractor or maintenance company Wessex RF & CA Mount House Mount Street Taunton TA1 3QE 01823 250116 Water Treatment Company for this assessment Aquastat Unit N – The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 OQE Tel: 01934 811264 Email – enquiries@aquastat.co.uk Mater Treatment Company for this assessment A ⁿ duastat Unit N – The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 OQE As above or email General Manager 1 st Company contact Gary Ford General Manager As above or email Jouise.blakemore@aquastat.co.uk Water Treatment company for Compliance tasks Aquastat Unit N – The Old Parlour Purn House Farm, Bleadon Purn House Farm, Bleadon Weston-Super-Mare Tel: 01934 811264 Email – enquiries@aquastat.co.uk	Deputy on site	Dean Bywood (barrack	Building 22, Wyvern	dean.bywood100@mod.gov.u
Major Chris Mills (QM)Wyvern Barracks01392 446688Water Supply CompanySouth West WaterPeninsula House Rydon Lane Exeter EX2 7HR01392 446688Mechanical contractor or Maintenance companyWessex RF & CAMount House Mount Street Taunton TA1 3QE01823 250116Image: Berger Supply Contractor or maintenance companyWessex RF & CAMount Street Taunton TA1 3QE01823 250116Image: Berger Supply Water Treatment Company for this assessmentMessex RF & CAMount House Mount Street Taunton TA1 3QE01823 250116Image: Berger Supply Major Contractor or maintenance companyMajor Chris Supply TA1 3QE01823 250116Image: Berger Supply Major Contractor or maintenance companyMount Street Taunton TA1 3QE01823 250116Image: Berger Supply Major ContactMount Street Taunton Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 0QETel: 01934 811264 Email - enquiries@aquastat.co.ukImage: Balakemore Company for this asser MagerAquastatUnit N - The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 0QEAs above or email gary.ford@aquastat.co.ukImage: Balakemore Compliance tasksAquastatUnit N - The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North SomersetTel: 01934 811264 Email - enquiries@aquastat.co.ukImage: Balakemore Supper-Mare Supper-Mare Compliance tasksAquastatUnit N - The Old Parlour Purn House Farm, Bleadon Balakemore BalakemoreTel: 019	responsible person	manager)	Barracks	<u>k</u>
Water Supply CompanySouth West WaterPeninsula House Rydon Lane Exeter EX2 7HR01392 446688Mechanical contractor or Maintenance companyWessex RF & CAMount House Mount Street Taunton TA1 3QE01823 250116Electrical contractor or maintenance companyWessex RF & CAMount House Mount Street Taunton TA1 3QE01823 250116Wessex RF & CAMount House Mount Street Taunton TA1 3QE01823 250116Water Treatment Company for this assessmentAquastatUnit N - The Old Parlour Purn House Farm, Bleadon BS24 0QETel: 01934 811264 Email - enquiries@aquastat.co.ukWater Treatment company for to asser MS CAAquastatUnit N - The Old Parlour Purn House Farm, Bleadon BS24 0QETel: 01934 811264 Email - enquiries@aquastat.co.ukWater Treatment company for company for Company contactLouise BlakemoreAs above or email gary.ford@aquastat.co.ukWater Treatment company for Compliance tasks as ner HSG274AquastatUnit N - The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 0QETel: 01934 811264 Email - enquiries@aquastat.co.uk		Major Chris Mills (QM)	Wyvern Barracks	
CompanyRydon Lane ExeterMechanical contractor or Maintenance companyWessex RF & CAMount House Mount Street Taunton01823 250116Electrical contractor or maintenance companyWessex RF & CAMount House Taunton01823 250116Electrical companyWessex RF & CAMount House Taunton01823 250116Wessex RF & CAMount House 	Water Supply	South West Water	Peninsula House	01392 446688
Image: Construction of the construction of construction of construction of companyWessex RF & CAMount House Mount House Mount Street Taunton Taunton TA1 3QE01823 250116Electrical contractor or maintenance companyWessex RF & CAMount House Mount House Mount Street Taunton TA1 3QE01823 250116Water Treatment Company for this assessmentAquastatUnit N - The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 QQETel: 01934 811264It Company contactGary Ford General ManagerAs above or email gary.ford@aquastat.co.ukenquiries@aquastat.co.ukWater Treatment company for this assessmentAquastatUnit N - The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 QQEAs above or email gary.ford@aquastat.co.ukUnit V - The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 QQEAs above or email gary.ford@aquastat.co.ukElectric@aquastat.co.ukWater Treatment company for this as ner HS6274AquastatUnit N - The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North SomersetAs above or email gary.ford@aquastat.co.ukWater Treatment company for	Company		Rydon Lane	
Image: Construction or companyWessex RF & CAMount House Mount Street Taunton TA1 3QE01823 250116Electrical contractor or maintenance companyWessex RF & CAMount House Mount Street Taunton TA1 3QE01823 250116Electrical contractor or maintenance companyWessex RF & CAMount House Mount Street Taunton TA1 3QE01823 250116Water Treatment Company for this assessmentAquastatUnit N – The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 0QETel: 01934 811264 Email - enquiries@aquastat.co.ukIt * Company contactGary Ford General ManagerAs above or email gary.ford@aquastat.co.ukWater Treatment company for company for Compliance tasks as ner HS6274AquastatUnit N – The Old Parlour Purn House Farm, Bleadon Bakemore Derenal ManagerAs above or email gary.ford@aquastat.co.ukWater Treatment company for compliance tasks as ner HS6274AquastatUnit N – The Old Parlour Purn House Farm, Bleadon BeadonTel: 01934 811264 Email - enquiries@aquastat.co.uk			Exeter	
Mechanical contractor or Maintenance companyWessex RF & CAMount House Mount Street Taunton TA1 3QE01823 250116Electrical contractor or maintenance companyWessex RF & CAMount House TA1 3QE01823 250116Electrical contractor or maintenance companyWessex RF & CAMount Street Taunton Taunton TA1 3QE01823 250116Water Treatment Company for this assessmentAquastatUnit N - The Old Parlour Purn House Farm, Bleadon BS24 0QETel: 01934 811264 Email - enquiries@aquastat.co.ukVater Treatment company for assessment1st Company contactGary Ford General ManagerAs above or email gary.ford@aquastat.co.ukWater Treatment company for company for compliance tasks as ner HSG274AquastatUnit N - The Old Parlour Purn House Farm, Bleadon Purn House Farm, Bleadon <br< td=""><td></td><td></td><td>EX2 7HR</td><td></td></br<>			EX2 7HR	
contractor or Maintenance companyMount Street Taunton TA1 3QEMount Street Taunton TA1 3QEElectrical contractor or maintenance companyWessex RF & CAMount House Mount Street Taunton TA1 3QE01823 250116Water Treatment Company for this assessmentAquastatUnit N – The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare BS24 0QETel: 01934 811264 Email - enquiries@aquastat.co.ukWater Treatment Company for this assessment1st Company contactGary Ford General ManagerAs above or email louise BlakemoreVater Treatment Company for Company for Company for Compliance tasks as ner HSG274AquastatUnit N – The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 0QEAs above or email louise BlakemoreWater Treatment Company for Compliance tasks as ner HSG274AquastatUnit N – The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BlakemoreTel: 01934 811264 Email - enquiries@aquastat.co.uk	Mechanical	Wessex RF & CA	Mount House	01823 250116
Maintenance companyTaunton TA1 3QETaunton TA1 3QEElectrical contractor or maintenance companyWessex RF & CAMount House Mount Street Taunton TA1 3QE01823 250116Water Treatment Company for this assessmentAquastatUnit N – The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare BS24 0QETel: 01934 811264 Email - enquiries@aquastat.co.ukIt is to company for Company for Compliance tasks as aper HSG274AquastatUnit N – The Old Parlour General ManagerTel: 01934 811264 Email - enquiries@aquastat.co.uk	contractor or		Mount Street	
companyTA1 3QEElectrical contractor or maintenance companyWessex RF & CAMount House Mount Street Taunton TA1 3QE01823 250116Water Treatment Company for this assessmentAquastatUnit N – The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 0QETel: 01934 811264 Email - enquiries@aquastat.co.ukVater Treatment Company for this assessmentAquastatUnit N – The Old Parlour Purn House Farm, Bleadon Be24 0QETel: 01934 811264 Email - enquiries@aquastat.co.uk1st Company contactGary Ford General ManagerAs above or email gary.ford@aquastat.co.ukWater Treatment company for Compliance tasks as per HSG274AquastatUnit N – The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare North Somerset BS24 0QETel: 01934 811264 Email - enquiries@aquastat.co.uk	Maintenance		Taunton	
Electrical Wessex RF & CA Mount House 01823 250116 contractor or Mount Street Taunton maintenance Taunton TA1 3QE Water Treatment Aquastat Unit N – The Old Parlour Tel: 01934 811264 Company for this Aquastat Unit N – The Old Parlour Email - North Somerset BS24 0QE enquiries@aquastat.co.uk 1st Company contact Gary Ford As above or email 2nd Company contact Louise Blakemore As above or email Unit N – The Old Parlour Tel: 01934 811264 Email - BS24 0QE Purn House Farm, Bleadon Email - Veston-Super-Mare North Somerset BS24 0QE 1st Company contact Gary Ford As above or email gary.ford@aquastat.co.uk 2nd Company contact Louise Blakemore As above or email Water Treatment Aquastat Unit N – The Old Parlour Tel: 01934 811264 Compliance tasks Aquastat Unit N – The Old Parlour Tel: 01934 811264 Purn House Farm, Bleadon Email - enquiries@aquastat.co.uk Weston-Super-Mare enquiries@aquasta	company		TA1 3QE	
contractor or maintenance companyMount Street Taunton TA1 3QEMount Street Taunton TA1 3QEWater Treatment Company for this assessmentAquastatUnit N – The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare BS24 0QETel: 01934 811264 Email - enquiries@aquastat.co.uk1st Company contactGary Ford General ManagerAs above or email gary.ford@aquastat.co.ukWater Treatment company for Company for Compliance tasks as per HSG274AquastatUnit N – The Old Parlour Purn House Farm, Bleadon BaseWater Treatment company for Compliance tasks as per HSG274AquastatUnit N – The Old Parlour Purn House Farm, Bleadon Purn House Farm, Bleadon Email - enquiries@aquastat.co.uk	Electrical	Wessex RF & CA	Mount House	01823 250116
maintenance companyTaunton TA1 3QETaunton TA1 3QEWater Treatment Company for this assessmentAquastatUnit N – The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare BS24 0QETel: 01934 811264 Email - enquiries@aquastat.co.uk1st Company contactGary Ford General ManagerAs above or email gary.ford@aquastat.co.uk2nd Company contactLouise Blakemore Purn House Farm, BleadonAs above or email louise.blakemore@aquastat.co.ukWater Treatment company for Compliance tasks as ner HSG274AquastatUnit N – The Old Parlour Purn House Farm, Bleadon Purn House Farm, Bleadon Purn House Farm, Bleadon Purn House Farm, BleadonTel: 01934 811264 Email - enquiries@aquastat.co.uk	contractor or		Mount Street	
companyTA1 3QEWater Treatment Company for this assessmentAquastatUnit N – The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare BS24 0QETel: 01934 811264 Email - enquiries@aquastat.co.uk1st Company contactGary Ford General ManagerAs above or email gary.ford@aquastat.co.uk2nd Company contactLouise Blakemore Purn House Farm, Bleadon ManagerAs above or email gary.ford@aquastat.co.ukWater Treatment company for Compliance tasks as ner HSG274AquastatUnit N – The Old Parlour Purn House Farm, Bleadon Meston-Super-Mare Purn House Farm, Bleadon Purn House Farm, Bleadon Weston-Super-MareTel: 01934 811264 Email - enquiries@aquastat.co.uk	maintenance		Taunton	
Water Treatment Company for this assessmentAquastatUnit N - The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare BS24 0QETel: 01934 811264 Email - enquiries@aquastat.co.uk1st Company contactGary Ford General ManagerAs above or email gary.ford@aquastat.co.uk2nd Company contactLouise BlakemoreAs above or email louise.blakemore@aquastat.co.ukWater Treatment company for Compliance tasks as ner HSG274AquastatUnit N - The Old Parlour Purn House Farm, BleadonWorth Somerset BS24 0QEDescription Gary Ford General ManagerAs above or email louise.blakemore@aquastat.co.ukWater Treatment company for Compliance tasks as ner HSG274AquastatUnit N - The Old Parlour Purn House Farm, Bleadon Weston-Super-Mare Purn House Farm, BleadonTel: 01934 811264 Email - enquiries@aquastat.co.uk	company		TA1 3QE	
Company for this assessment Purn House Farm, Bleadon Email - Assessment Weston-Super-Mare enquiries@aquastat.co.uk North Somerset BS24 0QE As above or email BS24 0QE Gary Ford As above or email gary.ford@aquastat.co.uk Company contact Gary Ford 2 nd Company contact Louise Blakemore As above or email Vater Treatment Aquastat Unit N – The Old Parlour Tel: 01934 811264 Compliance tasks Weston-Super-Mare enquiries@aquastat.co.uk	Water Treatment	Aquastat	Unit N – The Old Parlour	Tel: 01934 811264
assessment Weston-Super-Mare enquiries@aquastat.co.uk North Somerset BS24 0QE enquiries@aquastat.co.uk 1 st Company contact Gary Ford As above or email general Manager gary.ford@aquastat.co.uk 2 nd Company contact Louise Blakemore As above or email louise.blakemore@aquastat.co.uk Unit N – The Old Parlour Tel: 01934 811264 Water Treatment Aquastat Unit N – The Old Parlour Tel: 01934 811264 Compliance tasks Weston-Super-Mare enquiries@aquastat.co.uk as per HSG274 North Somerset North Somerset	Company for this		Purn House Farm, Bleadon	Email -
Morth Somerset BS24 0QE North Somerset BS24 0QE 1 st Company contact Gary Ford General Manager As above or email gary.ford@aquastat.co.uk 2 nd Company contact Louise Blakemore As above or email louise.blakemore@aquastat.co.uk Water Treatment company for Aquastat Unit N – The Old Parlour Purn House Farm, Bleadon Tel: 01934 811264 Compliance tasks as per HSG274 Weston-Super-Mare enquiries@aquastat.co.uk	assessment		Weston-Super-Mare	enquiries@aquastat.co.uk
Water Treatment company for Aquastat Unit N – The Old Parlour Tel: 01934 811264 Compliance tasks as per HSG274 North Somerset North Somerset North Somerset			North Somerset	
In Company contact Gary Ford As above or email General Manager gary.ford@aquastat.co.uk 2nd Company contact Louise Blakemore As above or email Vater Treatment Aquastat Unit N – The Old Parlour Tel: 01934 811264 Compliance tasks Purn House Farm, Bleadon Email - As above or email North Somerset enquiries@aquastat.co.uk			BS24 UQE	
Image: Contract General Manager gary.rord@aquastat.co.uk 2 nd Company contact Louise Blakemore As above or email Image: Data blakemore company for Compliance tasks Aquastat Unit N – The Old Parlour Tel: 01934 811264 Weston-Super-Mare enquiries@aquastat.co.uk		1. Company contact	Gary Ford	As above or email
Water Treatment Aquastat Unit N – The Old Parlour Tel: 01934 811264 Compliance tasks Weston-Super-Mare enquiries@aquastat.co.uk		and Course and court of		gary.ford@aquastat.co.uk
Water Treatment company for Aquastat Unit N – The Old Parlour Tel: 01934 811264 Compliance tasks Purn House Farm, Bleadon Email - as per HSG274 North Somerset North Somerset		2 ^m Company contact	Louise Blakemore	As above or email
company for Purn House Farm, Bleadon Email - Compliance tasks Weston-Super-Mare enquiries@aquastat.co.uk	Water Treatment	Δαμαστατ	Linit N – The Old Parlour	
Compliance tasks Weston-Super-Mare enquiries@aquastat.co.uk	company for	הקטמטנמנ	Purn House Farm Rleadon	Fmail -
as per HSG274 North Somerset	Compliance tasks		Weston-Super-Mare	enquiries@aquastat.co.uk
	as per HSG274		North Somerset	enquires@uquastatios.uk
BS24 OQE			BS24 OQE	

NB: If any of the above are not available at the time of inspection it may represent a gap in management procedures which could lead to a risk of infection through miscommunication. NNB: Any changes in the above structure must be recorded as soon as they take effect, and all parties must be notified.







6 SURVEY DETAILS:

6.1 MAINS WATER SUPPLY REPORT

Source of supply	Mains water
Number of mains cold water supply?	1
Location of main isolation valve?	Boiler room
Is there a water meter installed?	No
Is the pipework labelled?	Yes
Materials of construction	Copper
Are there any materials or fittings visibly present on the mains water system, that do not conform to the Water Regulations Advisory Scheme (WRAS) directory?	No
Mains water temperature °C (sentinel outlets)	Nearest Tap to Incoming Main: 10.C Furthest Tap from Incoming Main: 12.C
Are all other distribution temperatures that were tested within the correct temperature range? i.e. Below 20 °C?	Yes
Are there any non- flow through expansion vessels to any services on this system?	No
Is the pipework suitably insulated?	No
Does the cold-water supply have any inline filters including scale inhibitors/softeners?	No
COMMENTS	
Mains Water Supply Risk Score	Medium









6.1 MAINS WATER SUPPLY REPORT (continued)

Photos







6.2 **OTHER ASSETS REPORT**

Are dead legs / infrequently used outlets present within system pipework?	Yes, both
Are thermostatic mixer valves present on individual outlets?	No
Are there single mixer valves serving a number of outlets?	No
Is the mixed temperature of the pipework >1m?	-
Are flexible hoses fitted to any services on the mains water system?	Yes
Is there any unused equipment connected?	Yes, kitchen bib tap
Is any scale/debris present on any of the tap outlets?	No
Do any tap outlets have any spray or other inserts fitted?	No
Are strainers fitted?	No







6.3 COLD WATER STORAGE TANK REPORT

Tank Ref

:

CWST 1-2

Location	Exact location of tank		Above male ablu	tions	
Structure	Accurate dimensions lxwxh or	r dia	2 x 100 gallon ta	nks	
	Materials of tank and any joir	nting's	Plastic		
	Insulation type and thickness		Foil faced		
Lid Details	Is there a close-fitting lid		Yes		
	Is it securely fixed in place		Yes		
	Accurate dimensions for new	lid	N/A		
	Separate ball valve hatch		Yes		
	Vent size has it good rodent s	creen	Yes 1 "		
Overflow	Size and materials of main ov	erflow	1 ½ plastic		
	Is there a rodent filter		Yes		
	Size and materials of warning	pipe	N/A		
	Is there a rodent filter		-		
Supply	Size and materials of pipewor	'k	28mm copper		
	Fed from mains, softener or t	ank	Mains		
	Insulation type and thickness		Foam		
	Any other return or vent pipe	S	No		
Outlets	Size and Materials		Insulation type a	nd thickness	
Outlet 1	42mm copper		Hessian		
Outlet 2	42mm copper		Hessian		
Drain valve	Is there a drain valve – size if applicable	N/A			
Water in Tank	Temperature C	T1: 12.C		T2: 12. C.	
	Degree of sediment		Неаvy		
	Biological slime severe/mediu	ım/light	Light		
	Extent of corrosion		Nil		
	Is there adequate crossflow w	vithin the	Yes		
	Is the stored water over capa	citv??	No		
Labels	Is the tank labelled	,	Yes		
	Supply pipe labelled or coded		Yes		
	Outlets labelled or coded		Yes		
Operation	How far to adequate drain		20m		
	Power supply – volts/distance	2	20m		
	Is lighting adequate		Yes		
	Access limit ht x w		870 x 670		
CWST Risk Score			High		

Comments/Recommendations:







6. 3 COLD WATER STORAGE TANK REPORT (continued)

Photos











<u>6. 4</u> HOT WATER STORAGE REPORT

HWSV Ref : Cal 1

Location of hot water storage vessel	Boiler room
Construction	Stainless steel
Size of hot water storage vessel	253 litres
Horizontal/vertical	Vertical
Storage/non-storage	Storage
Main heat source	Gas
Supplementary heating	No
Insulation type	Pre insulated
Is there an open vent	No
Is there an Expansion Vessel	No
Size of Expansion Vessel	-
IS there a flow through Valve fitted?	-
Is there a drain fitted & what size?	-
What size is access hatch	220 mm
Is there a drain valve – if yes give size	Yes ¾ "
Does drain valve work	Not attempted
Condition of water from drain valve	-
Size and materials cold feed pipe	54 mm copper
Is cold feed valved	Yes
Fed from mains, tank or softened	Tank 1-2
Pressure gauge reading	-
Temp from main gauge on hot water flow	60.C
Temp from gauge on sec return flow	57.C
Safety valve size	3⁄4 "
Is system circulated by sec return (yes/no)	Yes
Is calorifier circulated	Yes
Anti-stratification Pump (yes/no)	No
Has pump got a time clock	-
If yes – how many hours is it set in any 24	-
Isolating valves on flow/return	No
Is calorifier labelled	Yes
Is pipe work coded/labelled	Yes
Power supply voltage/distance	5m
How far to adequate drain	5m
Periods of availability for working	By prior appointment
Access limit Height x width	2000 x 1200
Temperature from nearest hot outlet	60.C
Hot Water Storage Vessel Risk Score	Low

Comments/Recommendations:

Satisfactory •









HOT WATER STORAGE REPORT (continued) <u>6. 4</u>

Photos







6.5 SHOWERS & SPRAY OUTLETS

Site : Wyvern Barracks - Building 3

SHOWERS/SPRAY HEADS

Location	Nos of showers	Dismantled/ cleaned and disinfected YES/NO	Overall condition	Any repairs replacements	Regularity of Use		
Male ablutions	6	No	Good	2 x out of order	Unknown		
Female ablutions	8	No	Good No Unknown		Unknown		
COMMENTS:							
 Two male showers have been placed out of order, reinstate flow to all showers. Infrequently used showers should be flushed weekly. 							

Photos









6.6 SCHEDULE OF DEAD LEGS/BLIND ENDS

Site : Wyvern Barracks - Building 3

LOCATIONS	SYSTEM	ACTION
FF kitchen	Mains	Double check valve required at 'T off' to quick fill
Male showers	-	Reinstate flow to showers
Ground floor laundry	Hot and cold	Remove dead legs at source
Ground floor bar	Hot and cold	Isolated area. Reinstate flow or remove at source
Right side male WC	Mains	No flow to cold tap, reinstate flow to tap
Entrance female WC	Hot water	Reinstate flow to tap
Kitchen glass wash	Mains	Glass wash isolated. Remove or reinstate flow

PHOTOS:









PHOTOS:

Supply to FF kitchen quick fill. Fit a double check valve here	No flow to RHS ground floor male WC basin

Page 23 of 35









<u>6.7</u> **POINT OF USE WATER HEATERS**

					EXPANSIO	N VESSEL INFO
Water	Location	Make/model and capacity	Mains or	Full clean	Is there a	If yes – make model
Heater		of each heater	tank fed	possible	pressure vessel	and size and
					– Yes/No	whether fitted
ID						horizontally or
Number						vertically
1	GF male WC	Sadia 7	Mains	No	No	-
2	GF female WC	Santon 7	Mains	No	No	-
3	GF bar	Santon 7	Mains	No	No	-



For information purposes:

- All cold water should be stored at less than 20 degrees C. A.
- All hot water should be set to produce at least 45 degrees C at outlets after one running minute. Β.
- C. Temperatures between 20 degrees C at 45 degrees C produce ideal breeding ground for bacteria and should be avoided at all times.







6.8 FIRE HOSES

Fire hoses were not located on this site.

6.9 WATER SOFTENER

Water Softeners were not located on site.











WATER OUTLETS: SITE: Wyvern Barracks - Building 3 7.

Location	Sentinel	Cink		wc	Other	Chauser	Deth	Т	empera	ture	Flexible	Flexible	Flexible	Expansion	TN 4) // a	Mains	Tank	Hot	
Location	Outlet	ЗІПК	WHB	т/м	Other	Snower	Bath	Hot	Cold	Cold Blended	Hose	Vessels	I IVI V S	Тар	Тар	Тар	HW Source		
Kitchen WC	Y	-	1	1	-	-	-	65	15	-	0	-	-	-	1	1	Cal 1		
Main kitchen	-	5	1	-	1	-	-	61	15 13	-	0	-	-	1	4	6	Cal 1		
Bar	-	1	-	-	1	-	-	-	-	-	0	-	-	-	-	-	Isolated		
Laundry	-	1	1	-	3	-	-	61	15	-	2	-	-	-	2	2	Cal 1		
GF male WC	-	-	2	1	3	-	-	60	17	-	0	-	-	-	2	2	Cal 1		
GF female WC	Y	-	2	2	-	-	-	60	17	-	0	-	-	-	2	2	Cal 1		
RHS male WC	-	-	1	1	-	-	-	-	-	-	0	-	-	-	1	-	-		
RHS male WC	Y	-	1	1	-	-	-	50	17	-	0	-	-	-	1	1	Water heater		
RHS female WC	Y	-	1	1	-	-	-	-	17	-	0	-	-	-	1	1	Water heater		
FF kitchen	Y	1	-	-	1	-	-	61	12	-	0	-	-	1	-	1	Cal 1		
FF male ablutions	Y	1	6	5	-	6	-	61	15 10	-	12	-	-	1	6	7	Cal 1		
FF female ablutions	-	1	6	5	-	8	-	61	15 10	-	12	-	-	1	6	7	Cal 1		



Legionella

Control

Association



Water Outlet Legend:

SNK = Sink UR = Urinal DWF = Drinking Water Fountain HBT = Hose Bib Tap TMV = Thermostatic Mixing Valve ESH = Electric Shower QFL = Quick Fill Link EXP = Expansion Vessel CM = Coffee machine RH = Rinse Hose SPB = Spray Booth SO = Steam Oven BIB = Bib tap WHB = Wash Hand Basin TSH = Thermostatic Shower CWD = Chilled Water Dispenser WSM = Washing Machine HWB = Hot Water Boiler CAL = Calorifier BE = Blind Ends STR = Strainer MSH = Mixer shower CO = Combi Oven INF = Infrequently BID = Bidet TB = Tea Boiler WC = Water Closet WH = Water Heater VM = Vending Machine DSW = Dish Washer CMB = Combi Boiler PRU = Pressurisation Unit DL = Dead Leg EWC = Electronic Water Conditioner DWT = Drinking Water Tap FC = Fume Cupboard CDU = Chemical Dispensing Unit HWSV = Hot Water Storage Vessel





8. LINE DRAWINGS OF WATER SYSTEMS SITE: Wyvern Barracks - Building 3

NB: Due to the complexity of the pipe work at this site it is not possible to ensure the total accuracy of these line drawings. They may require revision.









SCHEMATICS KEY

		1		П	Humidifier
—	Mains Cold Water	¦	Dead-end	С	Drinking Water Chiller Unit
→	Tanked Cold Water	 	Dead-leg	V	Vending Machine
—	Hot Water Supply		Incoming Mains Stop Value	нwв	Hot Water Boiler
	Bore Hole Cold Water			СМ	Coffee Maker
	Soft Water	X _	Isolation Valve	DW	Dish wa she r
	Grey/Recycled Water	X	Isolation Valve (closed)	WM	Washing Machine
	Chemical Dosing Line	X- S	Solenoid Valve	SL	Sluice Cistern
	Room/Floor Border	R	Single non-return (check) Valve	SLM	Sluice Machine
	i i i i i i i i i i i i i i i i i i i	K40	Double non-return (check) Valve	WDU	Waste Disposal Unit
\sim	Incoming Supply	RPZ	Reduced Pressure Zone Valve (RPZ)		Potato Peeler
	Cold Water Storage Tank		Pressure Reducing Valve	ICE	Ice Making Machine
CWST			Pump	STM	Steamer
		 55	Thermostatic Mixing Valve	CSO	Combi Steam Oven
	Hot Water Storage Vessel		(TMV)	P	Pressure Gauge
HWSV	HOL WALET SLOTAGE VESSET	() () () () () () () () () () () () () (Thermostatic Mixer Tap (TMVT)	(T)	Temperature Gauge
	Combination Water Heater		Thermostatic Shower	M	Water Meter
			incrinostate shower		Heating
СѠН				HPU	Pressurisation unit
			Mixer Shower	CHPU	Chilled Water Pressurisation Unit
	Combi Boiler			NS	Mains cold Nearest sentinel point
СВ			Electric Shower	FS	Mains cold furthest
	High Storage Water Heater			MDS	Mains cold
нѕѡн					Multipoint sentinel
	Low Storage Water Heater		Cold Only Shower	NS	Nearest sentinel point
	Instanton ocus Mator I lo stor			FS	Furthest sentinel point
IWH	Instantaneous water Heater		Emergency Shower with	MPS	Tanked cold Multipoint sentinel
			Integral Header Tank		Borehole
рне	Plate Heat Exchanger				Nearest sentinel point
_₹ -	Strainer		Emergency Shower	FS	Furthest sentinel point
L .		│		MPS	Borehole Multipoint sentinel
Ľ	Inline Filter		Emergency Eye Wash	NS	Hot water Nearest sentinel point
	Ultra Violet Lamp				Hot water
•		📮	Hydro Tap	-	Furthest sentinel point
	Water Softener			MPS	Multipoint sentinel
				wc	Toilet
A	Expansion Vessel		Fire Hose Reel	UR	Urinal
	Feed and Expansion Tank			Whb	wash hand basin
		l.			





Page 29 of 35







<u>9.</u> **OTHER PHOTOGRAPHS**











10. ASSET REGISTER SUMMARY

Asset:	Asset Number of:			
Outlets	33			
Sentinel outlets	7			
Infrequently used outlets	Guided by site			
Cold Water Storage Tanks	2			
Hot Water Storage Vessel	1			
Plate Heat Exchangers	0			
Combi Boilers	0			
Point of Use Water Heaters - >15 Litres	0			
Point of Use Water Heaters - <15 Litres	3			
Instantaneous Water Heaters	0			
Combination Water Heaters (Fortic style)	0			
Combination Water Heaters with Storage (FBM style)	0			
Water Softeners	0			
Showers	14			
Rinse Hoses	1			
Spray Outlets	1			
TMVs	3			
TMTs	0			
Strainers	0			
Flexible Hoses	26			
Expansion Vessels	0			
Pumps	1			
RPZ Valve	0			





<u>11.</u> Water Treatment & Hygiene Experience and Training Details

All personnel undertaking water treatment and hygiene works must only be carrying out their duties if they are suitably qualified, trained and competent to do so. Details of the assessor for this risk assessment are recorded below:

Persons name:	Jon Barton
Job description:	Legionella Risk Assessor/consultant
Company:	Aquastat
Experience:	Working in the industry since 2011
Qualifications:	BSRIA pre-commissioning flushing course (March 2013)
	Risk Assessments of Water Systems (WMS October 2014)
	Level 2 Diploma in Plumbing Studies (City & Guilds 2013- 2014)
	Practical Legionella Risk Assessment (advanced) (WMS June 2015)
	Risk Assessing Cooling systems (WMS May 2017)
	Chlorine Dioxide training course – January 2019
	Legionella and the Law (WMS online course, April 2022)
	Legionella Causes and Impacts of Infection (WMS online course, April 2022)
	Evaporative Cooling Water Chemistry Foundation (WMS April 2022)

Certification for all the above are held at Aquastat offices.



Legislation and Codes of Practice 12.

References

1 Health and Safety at Work etc Act 1974 (c.37) The Stationery Office 1974 ISBN 978 0 10 543774 1

2 Control of substances hazardous to health (COSHH). The Control of Substances Hazardous to Health Regulations 2002 (as amended). Approved Code of Practice and guidance L5 (Sixth edition) HSE Books 2013 ISBN 978 0 7176 6582 2 www.hse.gov.uk/pubns/books/I5.htm

3 The Management of Health and Safety at Work Regulations 1999 SI 3242/1999 The Stationery Office

4 Reporting accidents and incidents at work: A brief guide to the Reporting of Injuries, Diseases and Dangerous Occurrences Regulations 2013 (RIDDOR) Leaflet INDG453(rev1) HSE Books 2013 www.hse.gov.uk/pubns/indg453.htm

5 The Notification of Cooling Towers and Evaporative Condensers Regulations 1992 SI 1992/2225 The Stationery Office

6 Consulting employees on health and safety: A brief guide to the law Leaflet INDG232(rev2) HSE Books 2013 www.hse.gov.uk/pubns/indg232.htm

7 Legionnaires' disease: A guide for duty holders Leaflet INDG458 HSE Books 2012 www.hse.gov.uk/pubns/indg458.htm

8 Managing for health and safety HSG65 (Third edition) HSE Books 2013 ISBN 978 0 7176 6456 6 www.hse.gov.uk/pubns/books/hsg65.htm

9 The control of legionella: A recommended Code of Conduct for service providers The Legionella Control Association 2013 www.legionellacontrol.org.uk

10 Water fittings and materials directory Water Regulations Advisory Scheme www.wras.co.uk/Directory

11 Water Supply (Water Fitting) Regulations 1999 SI 1148/1999 The Stationery Office

Further reading

BS 8580-1 2019 Water quality. Risk assessments for Legionella control. Code of practice British Standards Institution

BS 8558:2015 Guide to the design, installation, testing and maintenance of services supplying water for domestic use within buildings and their curtilages British Standards Institution

BS EN 806 (Parts 1-5) Specifications for installations inside buildings conveying water for human consumption British Standards Institution

Water systems: Health Technical Memorandum 04-01: Safe water in healthcare premises.

Code of Practice: Cooling water treatment Water Management Society 2007 www.wmsoc.org.uk

Getting specialist help with health and safety Leaflet INDG420(rev1) HSE Books 2011 www.hse.gov.uk/pubns/indg420.htm

Minimising the risk of Legionnaires' disease TM13 The Chartered Institution of Building Services Engineers 2013

Doc: AWRA1 -Appendice A



Control

Association





SUMMARY OF THE APPROVED CODE OF PRACTICE L8 (revised) and HSG274 Parts 1, 2 and 3 FOR THE PREVENTION OR CONTROL OF LEGIONELLOSIS

Any water system operating with temperatures of greater than 20C and which may release a spray or aerosol presents a reasonably foreseeable risk of Legionellosis. Experience shows that the following are the key systems, which required attention.

- Systems incorporating cooling towers or evaporative condenser.
- Hot water services
- Humidifiers and air washers.
- Spa baths and pools.
- Hot and cold water services in premises where the occupants are particularly susceptible.

For premises covered by the Health and Safety at Work Act 1974, the HSC's Approved Code of Practice requires the following:

- A risk assessment undertaken by a competent person to identify the risk of Legionellosis and any necessary and reasonably practicable precautionary measures required.
- A management plan identifying steps to be taken to minimise the risk. The plan should also identify the responsible persons, the lines of communication and the training and competence requirements for employees and sub-contractors.
- Implementation of the plan including training.
- Record keeping to track remedial activities and to monitor performance.
- The owner should ensure that the management system performance is audited and subject to management review to keep it relevant.

The following list provides an indication of the requirement of the ACOP, which is enforced by the Health and Safety Executive or the Environmental Health Department of the local authority, depending on your premises type. Failure to comply is not in itself an offence, but failure to comply may be taken by a court as proof that the person has contravened the legal requirements.

- * Risk Assessments
- * Management plan and procedure development
- * Training of personnel
- * Remedial action such as
 - cleaning and disinfection
 - Tank refurbishment
 - Regular water treatment (chemical/plant)
- * Provision of log books
 - Regular monitoring and system maintenance including sampling analysis, chemical cleaning and disinfection.

Doc: AWRA2 -Appendice B

Page 34 of 35







THE CONTROL OF LEGIONELLOSIS L8 SUMMARY FOR HOT & COLD-WATER SERVICES

L8 (Revised) and HSG274 Parts 1, 2 and 3 applies to all premises covered by the Health and Safety at Work Act 1974, where foreseeable risk of Legionellosis is present i.e. most commercial premises with a hot and cold water system

The prime focus of this document is to avoid conditions that permit Legionellae to proliferate and to avoid the creation of sprays or aerosols or where this is impracticable to minimise the release of droplets.

The conditions that promote legionellae proliferation are:

- Temperatures in the range of 20 45 C
- Presence of sediment, sludge, scale or organic matter which act as nutrients.
- Some unapproved water fittings may harbour legionella and act as a nutrient.
- High microbial levels may act as nutrients and as a host for legionellae.
- Biofilms and slimes may harbour and protect Legionellae from biocides. These are often caused by stagnant or low flow conditions.

The main areas of concern for hot and cold water services are shown in Table (1) along with some possible precautionary measures. A risk assessment should be carried out on each site and a management plan developed to minimise the risk. The management plan and its execution should be completely documented as detailed in Table (2).

ITEM	POSSIBLE PROBLEM	OPTIONS & PRECAUTIONARY MEASURES
Storage Tank	Stagnation	Location of inlet and outlet
	Temperature>20C	Ensure tanks not too large or numerous
	Sludge and Scale build up	Insulation, or low level chlorination
	Corrosion deposits build up	Clean and disinfect on regular basis
	Ingress of nutrients	Refurbishment/Butyl lining
		Tight fitting covers and insect mesh on overflow
Softeners & Filters	Deposit builds up	Backwash regularly
	Microbiological build up	Disinfect 6 monthly or as monitoring requires
	Fitting harbouring legionella	Use approved fittings only
Calorifiers	Stratification (temp<60C)	Pumped circulation or regular thermal
	Intermittent use	Disinfection
	Scale builds up	Thermal disinfection
		Pre-treat water or descale as required
Dead legs	Fittings harbouring legionella	Use approved fittings only
(e.g., taps, showers and	Stagnation	Chlorination and flush through
other appliances)		Thermal disinfection and flush through
		Keep pipe runs short
All pipework and systems	Sludge, Scale, Debris build up	Clean and disinfect on a regular basis
		Regular microbiological monitoring (e.g.
		Dip-slide 4 - 6 per annum
		Legionella sampling annually

TABLE 1 - TYPICAL RISKS IN HOT AND COLD WATER SERVICES

RECORDS FOR HOT AND COLD-WATER SERVICE

A log book with the following contents is recommended: -

- Identification of those responsible and lines of communication.
- Description and plan of the system.
- Risk Assessment.
- Operation of the system.
- Procedures for inspection and checking of the system.
- Management plan of remedial activities and records of progress.
- Records of:
 - Water temperatures Record of operation, maintenance and checking Inspection record and subsequent action.
 - Cleaning and disinfection record

Doc : AWRA3 - Appendice C



