

Project Number 2481

Management Asbestos Survey Report

Wyvern Barracks, Barrack Road, Exeter, Devon, **EX2 6AE (No Access Buildings)**







Working in Partnership with Shield Environmental Services Shield



Document Name	Author	Issued by	Revision Number	Issue Date	Page No
2019	Emma Humphreys	Armour AS	0	03/07/2019	1



Contents

Section	
1	Contacts & Authorisation
2	Executive Summary
3	Site Description & Survey Information
4	Positive and Presumed Photos Sheets
5	Negative Photos Sheets
6	Survey Objectives
7	Survey Techniques
8	Survey Caveat
9	Survey Notes
10	Material Assessment Algorithm
11	Certificates of Bulk Analysis
12	Site Plan

Document Name	Author	Issued by	Revision Number	Issue Date	Page No
2019	Emma Humphreys	Armour AS	0	03/07/2019	2



Section 1: Contact Details

Client Details:		Instructing Party:		
Wessex RFCA Mount House Mount Street Taunton		Shield Environmental Shield House Caxton Business Park Crown Way		
TA1 3QE		Bristol BS30 8XJ		
Contact Name:	Sue Morrell	Contact Name:	Chloe Smith	
Tel: 01823250115	Fax: N/A	Tel: 01173012650	Fax: N/A	

Site Address: Wyvern Barracks Barrack Road Exeter Devon EX2 6AE		Report Author: Armour Analytical Admirals Yard Station Road Bristol BS34 6LR	
Contact Name:	Andy Palmer	Contact Name:	David Kelly
Tel: 07775560719	Fax: N/A	Mobile: 0776970	7519

Lead Surveyor's Name:	Lead Surveyor's Authorising Signature:
D. Kelly	
	Welly

Document Name	Author	Issued by	Revision Number	Issue Date	Page No
2019	Emma Humphreys	Armour AS	0	03/07/2019	3



Section 2: Executive Summary

No Samples were taken during this survey.

The following items have been Presumed to be Asbestos Containing Materials as they were not accessible at the time of the survey:

```
Item 1 - Building 15 - Squash Court - No access within the building as it was locked
```

Item 2 - Building 12 - No access within the building as it was locked

Item 3 – Building 16 – Armoury – No access within the building as it was locked

The presence of asbestos in these areas cannot be ascertained at this time. If any works are to be carried out in these areas in the future, then these works should be approached cautiously.

In accordance with current legislation, any suspect materials encountered in these areas are to be assumed to contain asbestos until proven otherwise. This will normally involve cessation of works in the affected area.

Document Name	Author	Issued by	Revision Number	Issue Date	Page No
2019	Emma Humphreys	Armour AS	0	03/07/2019	4



Section 3: Site Description & Survey Information

Brief description on the general building construction

Brick and block construction with pitched and flat roofs.

Caveat for no access areas

No access was possible to Building 15 (Squash Court) or building 12 as access could only be gained through yeomanry, as advised by Andy Palmer. Despite several attempts over a week period the yeomanry could not be located. No access was possible to building 16 (Armory) as it was a secured store and there was no officer on site that could give me access during the week of the survey, as advised by Andy Palmer.

EXTERNAL MATERIALS	
Roof Type	Pitched
Roof Materials	Tiles, Felt
Soffits	Concrete
Fascia	Timber
Walls	Brick
Verge Under cloaking	N/A
Guttering	Metal, Plastic
Downpipes	Plastic, Metal
Window/Door frames	Aluminium
Other Materials	N/A
INTERNAL MATERIALS	
Loft Insulation	No access
Roof Underlining	No access
Ceilings	No access
Walls Internal	No access
Floors	No access
Doors/Frames	No access
Pipework/Insulation	No access
Boxings	No access
Boiler Make	No access
Flue Pipes	No access
Storage Heaters	No access
Electrical Boxes/Machinery	No access
Ducting/Risers	No access
Stairs	No access
Lift Shafts	No access
Other Materials	No access

Document Name	Author	Issued by	Revision Number	Issue Date	Page No
2019	Emma Humphreys	Armour AS	0	03/07/2019	5



Section 4: Positive and Presumed Photos Sheets

Item No: 1 Sample No: N/A

Location: Building 15 - Squash Court



Material Description:	No access within building as locked			
Identification:	Presumed to Contain Asbestos			
Approx. quantity:	X 1 Building			
Accessibility	Low Assessment Score			
Product type:	No Access 3			
Extent of Damage:	No Access 3			
Surface Treatment:	No Access	3		
Asbestos type:	No Access 3			
	Material Assessment Score:	12		
	Priority Assessment Score:	High		
Action:	Further Investigation Needed			
Comments:	Access could only be gained through yeomanry, as advised by Andy Palmer. Despite several attempts over a week period the yeomanry could not be located.			

Document Name	Author	Issued by	Revision Number	Issue Date	Page No
2019	Emma Humphreys	Armour AS	0	03/07/2019	6



Item No: 2 Sample No: N/A

Location: Building 12




Material Description:	No access within building as locked				
Identification:	Presumed to Contain Asb	estos			
Approx. quantity:	quantity: X 1 Building				
Accessibility	Low	Assessment Score			
Product type:	No Access	3			
Extent of Damage:	No Access	3			
Surface Treatment:	No Access	3			
Asbestos type:	No Access	3			
	Material Assessment Score:	12			
	Priority Assessment Score:	High			
Action:	Further Investigation Nee	eded			
Comments:	Access could only be gained through yeomanry, as advised by Andy Palmer. Despite several attempts over a week period the yeomanry could not be located.				

Document Name	Author	Issued by	Revision Number	Issue Date	Page No
2019	Emma Humphreys	Armour AS	0	03/07/2019	7



Item No: 3 Sample No: N/A

Location: Building 16 - Armoury



Material Description:	No access within building as	locked		
Identification: Presumed to Contain Asbestos				
Approx. quantity:	Approx. quantity: X 1 Building			
Accessibility	Low	Assessment Score		
Product type:	No Access	3		
Extent of Damage:	No Access	3		
Surface Treatment:	No Access	3		
Asbestos type:	No Access	3		
	Material Assessment Score:	12		
	Priority Assessment Score:	High		
Action:	Further Investigation Nee	eded		
Comments:	This building is a secure store and there was no officer on site during the week of the survey that had access to this building, as advised by Andy Palmer.			

Document Name	Author	Issued by	Revision Number	Issue Date	Page No
2019	Emma Humphreys	Armour AS	0	03/07/2019	8



Section 5: Negative Photos Sheets

No negative items were found during the survey.

Document Name	Author	Issued by	Revision Number	Issue Date	Page No
2019	Emma Humphreys	Armour AS	0	03/07/2019	9



Section 6: Survey Objectives

Instructions were received from Sue Morrell of Wessex RFCA to carry out a Management asbestos survey at Wyvern Barracks, Barrack Road, Exeter, Devon, EX2 6AE in accordance with HSG264 and Armour Analytical's quality procedures.

The survey was carried out on 21^{st} June 2019 by David Kelly with the objective of facilitating a Management report.

This Management survey is characterised as a 'Visual Inspection Sampling and Identification Survey' in HSG264. This type of survey is used to locate and describe, so far as is reasonably practicable, all asbestos containing materials (ACMs) in the building and will by its nature involve the partial destruction of the building's fabric as access is gained to all areas. A full sampling programme is undertaken to identify possible ACMs and estimate the extent of ACMs reported.

The objective of this survey report is to identify, so far as is reasonably practicable, the location, extent, product type and composition of ACMS within the building to enable the building occupants to put management and remedial procedures in place.

Document Name	Author	Issued by	Revision Number	Issue Date	Page No
2019	Emma Humphreys	Armour AS	0	03/07/2019	10



Section 7: Survey Techniques

Each floor, room and area within the scope was systematically inspected for suspect materials thought or known to contain asbestos and where such materials were encountered their location, extent, and composition were recorded.

Where materials of a similar nature exist, to those previously sampled, and a reasoned argument can be made that their composition is likely to be identical further physical sampling was not undertaken.

Photographs were taken of all sample locations, unless otherwise stated.

The analysis of suspect ACMs was undertaken by a UKAS accredited laboratory using the analytical method detailed in *HSG248*, *Appendix 2 -Asbestos: The analysts' guide for sampling, analysis and clearance procedures.*

Document Name	Author	Issued by	Revision Number	Issue Date	Page No
2019	Emma Humphreys	Armour AS	0	03/07/2019	11



Section 8: Survey Caveat

This report is based upon a management report inspection of an unfamiliar site. During the course of the survey all reasonable efforts were made to identify the physical presence of materials containing asbestos within the building.

A Management Survey is a non-intrusive survey, meaning that access within the fabric of the building is limited. The survey does not include access to the following areas (unless agreed beforehand with the Client and provisions are put in place):

- Within wall or ceiling construction;
- Under fixed flooring;
- Within non-openable boxings;
- Within live electrics, boilers or machinery;
- Where access/visibility is limited in an area due to stored items, furniture or services;
- Areas where there is no safe access to inspect such as floor ducts, lift shafts and loft spaces with no crawlboards;
- High level areas that are too high to safely inspect.
- Within pipework insulation throughout building as this would affect the integrity of services.

Any intrusive works carried out within the building must first be subject to a Refurbishment Asbestos Survey.

This report will be restricted to the areas that fall within the scope of works for project and will not take into account any area's that do not fall within the scope. Any asbestos that is identified within this report will need to be added to the buildings existing information and should not form the basis for a management survey. This survey will not include priority assessments nor will it include a register.

This survey considered the construction of the building, associated fixtures & fittings and associated structures and in no way should it be considered as a ground investigation report.

Services should be disconnected prior to commencement of a Management survey; however, where plant and/or electrical installations are live or appear to be live then these will not be accessed.

This survey report is not a bill of quantities.

Document Name	Author	Issued by	Revision Number	Issue Date	Page No
2019	Emma Humphreys	Armour AS	0	03/07/2019	12



Section 9: Survey Notes

This report has been written with reference to the various Guidance Notes etc, issued, and current at the date of this report and describes circumstances at the site on the date the investigation took place.

Where similar items exist in the building, only one or two samples have been taken to ascertain the material content. It was assumed that similar products were of the same material.

Any person undertaking work within the buildings should be told of the presence of asbestos. This briefing also applies to any other person associated with the site, including staff, subcontractors and others.

The drawings in the report are not to scale and are illustrative only to indicate approximate locations. The descriptions used are for location identification purposes.

All the recommendations described in this report are based upon assumptions made after consideration of the type of material, condition of the material, its location, analysis result and type of use the area is thought to be subjected to. However, statutory authorities or others could require amendments based on local knowledge, change in legislation, change in use or indeed other conditions or criteria.

Samples taken from floor tiles (or similar material) may include a bitumen adhesive as part of the sample. It is known that some proprietary brands of bitumen have an asbestos content and this will be included as an integral part of the bulk sample unless otherwise stated.

Document Name	Author	Issued by	Revision Number	Issue Date	Page No
2019	Emma Humphreys	Armour AS	0	03/07/2019	13



Section 10: Material Assessment Algorithm

Variable	Score	Examples
Installation / Product type	1	Vinyl, 'Bakelite', Cement
/1	2	Asbestos insulating board, paper, rope
	3	Pipe insulation, spray coating, friable debris
Condition / damage	0	Good
	1	Slight / minor damage
	2	Moderate damage – breakage to surface treatment
	3	Major damage – smashed or exposed material
Surface treatment	0	Non-friable e.g. vinyl
	1	Enclosed insulation, encapsulated AIB
	2	Unsealed AIB, encapsulated insulation
	3	Unsealed insulation or spray coating
Asbestos type	1	Chrysotile
	2	Amosite & other amphiboles
	3	Crocidolite

The scores from each of the four sections are added together to produce a risk score:

Risk score	Risk assessment	
10 or more	High risk	
7 – 9	Medium risk	
5 – 6	Low risk	
4 & below	Negligible risk	

Document Name	Author	Issued by	Revision Number	Issue Date	Page No
2019	Emma Humphreys	Armour AS	0	03/07/2019	14



Section 11: Certificates of Bulk Analysis

No samples were taken during this survey.

Document Name	Author	Issued by	Revision Number	Issue Date	Page No
2019	Emma Humphreys	Armour AS	0	03/07/2019	15



KEY

Visual Inspection

ACM's Detected (Positive Items)

> No ACM's Detected

(Negative Items)

Presumed to Contain ACM's

No Access

Section 12: Site Plan



Document Name	Author	Issued by	Revision Number	Issue Date	Page No
2019	Emma Humphreys	Armour AS	0	03/07/2019	16



I the surveyor can confirm that this report is accurate to my findings onsite and this survey has been Content checked by myself.

Checked by: David Kelly

Date: 03/07/2019

I the Admin Manager can confirm that this report is accurate to the paperwork received and this survey has been quality checked by myself.

Checked by: Emma Humphreys

Date: 01.07.2019

Report Compiled By

Armour Analytical Services Ltd, Admirals Yard, Station Road, Bristol, BS34 6LR

Document Name	Author	Issued by	Revision Number	Issue Date	Page No
2019	Emma Humphreys	Armour AS	0	03/07/2019	17